AUTODESK® NAVISWORKS® 2019 Update 1

Guide to features and enhancements

August 2018

Please send feedback on this guide to: navisworks.productmanager@autodesk.com

Introduction

Thanks for downloading the Navisworks® 2019 Update 1

This update includes several enhancements and fixes, many of which have been identified by you. Your opinion really matters to us. It helps us to continually improve Navisworks and provide the best possible solution to you, our customers!

If you see any more issues in this release, don't hesitate to report them! We value your insight, continued business, and feedback.

Many thanks,

The Navisworks Team

Primary issues resolved by the Update

The Navisworks 2019 Update 1 provides fixes for the following issues:

Issue Type	Summary	ID
Improvement	[LMV] Support .VUE file property	NW-54042
Improvement	IFC Class and Element description in IFC hierarchy incorrect	NW-53825
Improvement	AVEVA E3D import (RVM file format) – Missing attributes in the object properties.	NW-53726
Improvement	Allow Display ID to be shown in TimeLiner Overlay text	NW-53888
Improvement	Add a space between the date and time in TXT Clash Report exports	NW-53966
Improvement	Read shared parameters in corresponding to IFC data	NW-54290

Issue Type	Summary	ID
Bug	TimeLiner Auto Attach not working on certain Category/Property	NW-54118
Bug	SceneConvertServer doesn't shutdown	NW-54163
Bug	Setting global options via API or XML file has no affect with out-of-process loaders.	NW-54155
Bug	ArchiCAD21 cannot export nwc with error "Cannot write output file"	NW-54174
Bug	Cannot Check ArchiCAD21 in Configure Installation dialog when install NW Exporter2019	NW-54167
Bug	C++ error rendering a model	NW-54166
Bug	Navisworks does not display anything if the assembly is saved in a substitute LOD	NW-54011
Bug	Navisworks Manage 2018 - crash with CER during Save	NW-53822
Bug	CER when load IFC file after install IFC for Revit	NW-54285
Bug	Navisworks License Timeout	NW-54195
Bug	Multi-threaded Clash, crashing with a point cloud data set	NW-54250
Bug	A Chinese translation mistake in Archicad config file nwexportarchicad.name	NW-54236

Cont.

Issue Type	Summary	ID
Bug	ArchiCAD21 Exporter options display unreadable code in localization OS.	NW-54232
Bug	Exported NWC and Glued model are not what is displayed in Revit	NW-54181
Bug	English Language Pack - Spanish category objects in selection tree	NW-53410
Bug	Revit to Navisworks Export is excluding certain instances of family	NW-53654
Bug	Navis exporter progress dialog issues	NW-53657
Bug	Global Options overrides are not passed onto SceneConvertServer	NW-45042
Bug	some files cannot be loaded with internal error	NW-53996
Bug	Cannot load rvt because of an internal error	NW-53964
Bug	Navisworks 2018 crashes with saving file	NW-53939
Bug	Embedded texture is not displayed while opening NWD file	NW-52557

End.