Autodesk® Fabrication ESTmep™ 2018.3.0 Update Enhancements List

The following improvements and fixes have been made in Autodesk® Fabrication ESTmep™ 2018.3.0 Update, build 3.06.844:

Note: This update is available only to students and to Autodesk subscribers of Autodesk® Fabrication $ESTmep^{TM}$.

- Added the ability to minimize the in-canvas widgets.
- Changed the script file format from UTF-8 to ANSI by default.
- Fixed an issue that caused multiple-item-properties to fail to update the item custom data fields.
- Fixed an issue that resulted in an error when attempting to access sealant information on parts that do not support sealant.
- Improved pattern 1243 to allow the rod length to be shortened using the in-canvas grip.
- Improved pattern 2189 to include more body/top options.
- Improved pattern 2522 to accept negative values for the Right Collar dimension.



Autodesk® Fabrication ESTmep™ 2018.2.0 Update Enhancements List

The following improvements and fixes have been made in Autodesk® Fabrication ESTmep™ 2018.2.0 Update, build 3.06.816:

Note: This update is available only to students and to Autodesk subscribers of Autodesk® Fabrication $ESTmep^{TM}$.

- Improved Item List view in Job contents table to auto-refresh when parts are deleted.
- Improved the stability of patterns 1206 & 1207 when adding holes.
- Improved the estimating information present on the Review Installation Costs, Review Installation Times, and Review Fabrication Time tabs.
- Fixed an issue causing hangers to report incorrect costs.
- Improved patterns 2884 & 2051 by relaxing the bad dimension checks.
- Improved connector insulation adjustments when insulation parts = Wrap inside.

Autodesk® Fabrication ESTmep™ 2018.1.0 Update Enhancements List

The following improvements and fixes have been made in Autodesk® Fabrication ESTmep™ 2018.1.0 Update, build 3.06.739:

Note: This update is available only to students and to Autodesk subscribers of Autodesk® Fabrication $ESTmep^{TM}$.

- CID 2884 & 2051 Improved bad dimension checks.
- CID 64 Improved notches on developments.
- CID 854 Improved connector visibility.
- CID 883 Improved bad dimension checks.
- CID's 2182, 2183, & 2184 Improved connector drawing detail.
- CID's 379, 383 & 832 Improved developments when branch diameter is greater than the pipe diameter.
- CID's 52,53,54,92,169,173,323,341& 811 Improved reporting out collar quantity for reducers.
- Improved Design Line when filling in RedEOLTee while adding branches.
- Improved Design Line when filling in terminals that are larger than the connected line.
- Improved dynamic hole developments when the depth of the straight is larger than the width.
- Improved Fabrication Times for straights when Double Wall is turned on/off.
- Improved pasting product list text entries from Excel when creating content.
- Improved specification to select the relevant value for straight duct pieces.
- Improved stability when editing insulation specification in the database.
- Improved support for cutting in hangers onto insulated pipe.
- Improved tracking in the 3D viewer to prevent objects from being deleted unexpectedly.
- Improved valve handle option when inline with body.

