

# Autodesk® Fabrication ESTmep™ 2019.1.0 Update Enhancements List

The following improvements and fixes have been made in Autodesk® Fabrication ESTmep™ 2019.1.0 Update, build 3.07.545:

**Note:** This update is available only to students and to Autodesk subscribers of Autodesk® Fabrication ESTmep™.

- Added API to read pipe end type information on connectors.
- Added part costing units to the API.
- Added the ability to minimize the in-canvas widgets.
- Added the pattern number to fabrication scripts.
- Fixed an issue that caused multiple-item-properties to fail to update the item custom data fields.
- Fixed an issue that caused new item folders to be created in a disabled state.
- Fixed an issue that caused services to vanish after purging the database.
- Fixed an issue that caused the NumPad to lose focus after interacting with other areas of the user interface.
- Fixed an issue that stopped the connector edit dialog from displaying when editing multiple connectors.
- Fixed an issue that stopped the folder path from inheriting the folder name when adding new folders.
- Improved pattern 1243 to allow the rod length to be shortened using the in-canvas grip.